

word

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
Takayuki YAGI et al.)	Examiner: K. T. Nguyen
Application No.: 09/819,672	:	Group Art Unit: 2881
Filed: March 29, 2001	;	
For: ELECTRON OPTICAL SYSTEM ARRAY, CHARGED-PARTICLE BEAM EXPOSURE APPARATUS USING THE SAME, AND DEVICE	:) :)	July 15, 2005
MANUFACTURING METHOD	:	Certificate
U.S. Patent No. 6,872,951 B2) : :	JUL 2 1 2005
Issued: March 29, 2005) :	of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and
Trademark Office due to errors which appear in the printed patent as a result of Patent and
Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent
and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit

Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentees' undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our belowlisted address.

Respectfully submitted,

Attorney for Patentees

Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

Facsimile: (212) 218-2200

SEW/eab

DC_MAIN 209313v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,872,951 B2

DATED : March 29, 2005

INVENTOR(S): Takayuki YAGI et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE:

In item "(56) References Cited." under "OTHER PUBLICATIONS," in the first line of the first-listed article, "Minature" should read -- Miniature --.

COLUMN 1:

Line 35, "beams" should read -- beam system --.

COLUMN 2:

Line 21, "suffers" should read -- suffers from --.

Line 25, "destruct" should read -- destroy --.

Line 46, "destruct" should read -- destroy --.

Line 52, "arts." should read -- art. --.

COLUMN 3:

Line 11, "includes" should read -- include --.

Line 50, "dice or" should read -- a die or --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,872,951 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile
FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,872,951 B2

DATED : March 29, 2005

INVENTOR(S): Takayuki YAGI et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 56, "arrays" should read -- array --.

COLUMN 10:

Line 67, after "excellent", the right margin should be closed up.

COLUMN 11:

Line 17, after "1010", the right margin should be closed up.

COLUMN 12:

Line 30, after "factory.", the right margin should be closed up.

Line 49, "a trouble" should read -- trouble --.

COLUMN 13:

Line 11, "and.," should read -- and --.

Line 55, "a trouble" should read -- trouble --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,872,951 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile
FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,872,951 B2

DATED : March 29, 2005

INVENTOR(S): Takayuki YAGI et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 4, "number" should read -- member --. Line 11, "system" should read -- array --.

COLUMN 16:

Line 28, "arrange" should read -- arranged --.

COLUMN 17:

Line 9, "electrodes" should read -- electrode --.

Line 20, "intermediated" should read -- intermediate --.

Line 24, "optical" should read -- optical system array --.

Line 25, "image" should read -- images --.

COLUMN 18:

Line 20, "intermediated" should read -- intermediate --.

Line 23, "structure" should read -- structures --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,872,951 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82) No. of add'l. copies @ 30¢ per page

□ ___